

## PEOPLES' COMPRESSORS & SYSTEMS

<u>PNG Compressor</u>	<u>Compressor Units</u>	<u>System Number Affected</u>	<u>System Name</u>	<u>Regulator Set Point</u>
<b>Egry</b>	#1	1196	Tunnelton Production	48#
<b>Creekside</b>	#1	642	Valley Indiana	82#
<b>Latrobe</b>	#1	442A	Central Div. Belt	75#
<b>Belknap</b>	#1 & #2	1138	Baum to Truittsburg Production	48#
<b>Girty</b>	#1 & #2	643	Girty Indiana(can also backup #3,#4)	185#
	#3 & #4	1136	Girty to Valley Production	48#
		1135	Roaring Run to Girty Production	48#
<b>Redbank</b>	#1	1138	Baum to Truittsburg Production	48#
<b>Shady Plain</b>	#1	1136	Girty to Valley Production	48#
		1135	Roaring Run to Girty Production	48#
<b>Valley</b>	#1	1136	Girty to Valley Production	48#
		1138	Baum to Truittsburg Production	48#
	#3	643	Girty Indiana	185#
	#4	368	Rural Valley to Dayton	90#
		320	Valley to Kittanning	90#
	#5	643	Girty Indiana	185#
<b>Arnold</b>	#1 - #2	649	Merwin Roaring Run Vandergrift	95#
		650	Leechburg UE E Co	95#
		489	Northern to Murrys ville	95#
<b>Mendon</b>	#1	442B	Central Div Belt Sys	75#
<b>Armbrust</b>	#1	442C	Central Div Belt Sys	75#
<b>Merwin</b>	#1	185	North Washington	North - 30# South - 34#
<b>Roaring Run</b>	#1	185	North Washington	30#
		1135	Roaring Run to Girty Production	48#
<b>Limestone</b>				
<b>Fisher</b>				
<b>Village</b>				
<b>Atwood</b>				
<b>Crooked Creek</b>				
<b>Shoemaker</b>				
<b>Creighton</b>				
<b>Sprankle</b>	#1 - #2 - #3	200	Sprankle Mills to Burford Jct	45#
<b>Alabran</b>	#1 - #2	402	Trade City to Kittanning	45#
<b>Kinter</b>	#1 to #6	503	Kintersville to Indiana	45#
<b>Schmidt</b>	#1 - #2	555	Saltsburg to North Washington	30#